














Cooling

Description	Year	Model	Part No.	Price	Notes
Water Pumps & Gaskets	1942-63	Champion 6 cyl & 1949-58 trucks with 170 & 185 c.i. engine, includes gasket,	682630	\$165 ea	
	1951-64	All V8 exc. Avanti, complete new HD pump (not exchange) includes gasket,	527070	\$150 ea	
	1963-64	Avanti pump, complete new HD pump (not exchange) includes gasket,	1564459	\$170 ea	
	1939-64	Champion water pump gasket,	534597	\$4 ea	
	1951-64	V8 Water pump gasket,	527246	\$4 ea	
Water Manifold Studs & Gaskets	1951-64	V8 Water manifold mounting bolt for generator/alternator adjusting arm,	527255	\$8 ea	
	1958-64	Stud for mounting Eaton power steering pump (long hexagonal section),	1547363	\$28 ea	
	1958-64	Stud for mounting Eaton power steering pump (short hexagonal section),	1547364	\$28 ea	
	1951-64	V8 Upper water manifold gasket,	527240	\$2 ea	
	1951-64	V8 Lower water manifold gasket,	527856	\$2 ea	
Fans & Viscous Hubs	1962-64	V8 Viscous fan clutch for Avanti powered cars or with factory air conditioning, (used with 5 or 6 blade fan),	1560257	\$130 ea	 Used Used Used
	1963-64	V8 Fan (5 blade) for use with above viscous fan hub, improves cooling,	1558715	\$160 ea	
	1960-64	Champ p-u fan (4-blade), also for 1953-58 Champion & 6 cyl Lark,	534736P	\$20 ea	
	1960-64	Champ p-u fan (6-blade) for heavy duty or export models,	1692920P	\$50 ea	
	1961-64	V8 fan (4-blade) for most cars without air conditioning,	1556168	\$20 ea	
Fan Belts	1947-53	6 cyl Fan/Generator belt for Champion, M-Series & 2R trucks,	518461	\$30 ea	
	1951-55	V8 Fan/Generator belt, also for 1961-62 Lark & Hawk with Air Conditioning,	529374	\$15 ea	
	1959-64	V8 Fan/Alternator belt for Lark & Hawk without Air Conditioning,	1563072	\$25 ea	
	1965-66	V8 Fan/Alternator belt for all models without Air Conditioning,	1694315	\$23 ea	
Fan Pulleys (on water pump)	1955-64	V8 fan drive pulley for all exc. Avanti powered cars (7 3/8" dia),	536739	\$45 ea	N.O.S.
	1959-64	V8 pulley for cars with factory air con. or viscous fan hub (6 1/4" dia),	534735	\$65 ea	
	1963-64	Avanti 3-groove water pump pulley, without air conditioning,	1556483	\$130 ea	N.O.S. Used
	1965-66	V8 Crank drive pulley for power steering,	1564776	\$25 ea	
		<i>Many other used pulleys available.</i>			
Water Temperature Senders	1959-64	Sender for 6 cyl.	1549452	\$35 ea	
	1957-64	Sender for all V8,	1545220	\$38 ea	
	1965-66	Sender for 6 cyl & V8,	1565609	\$58 ea	
Radiator Caps	1955-66	14 psi cap, zinc plated, looks just like the original with S.M.Co stamping,	1551190	\$38 ea	
	1955-66	13 psi cap, same as above but Tridon,	1551190R	\$12 ea	
	1961-66	7psi cap for cars with <u>Australian made radiators</u> ,	1551190A	\$12 ea	

Thermostats	1938-60	160 degree thermostat, for 1938-42 cars, 1947-50 Commander, 1951-60 V8,	533247	\$25 ea	
	1939-66	160 degree thermostat, for 1939-58 Champion & 1961-66 V8 inc. Avanti,	1560842	\$18 ea	
Thermostat Housings & Gaskets	1953-60	Thermostat housing for 1953-54 Commander & 1956-60 Hawk V8, includes gasket,	532383	\$40 ea	
	1961-64	Thermostat housing for 6 & V8, includes gasket, all including Avanti,	1550844	\$40 ea	
	1939-60	Thermostat housing gasket, Champion, 2R and M series trucks,	194660	\$2 ea	
	1939-60	Thermostat sleeve gasket, for Champion, 2R and M series trucks,	194658	\$2 ea	
	1939-60	Champion thermostat spacer steel ring),	196709	\$15 ea	
	1951-60	Therm. housing gasket, all V8 (4 holes),	527284	\$3 ea	
	1961-64	Therm. housing gasket, all 6 & V8, correct shape and thickness, self adhesive,	1550816	\$6 ea	
	1965-66	Housing gasket, all 6 & V8,	1564066	\$3 ea	
Heater & Climatizer Parts	Most cars	Heater hose fire wall grommet, suitable for 3/4 dia. Hose,	1556859	\$6 ea	Various used N.O.S. N.O.S.
	1959-60	Heater tap for Lark & 1960-64 Champ pick-up, call for availability,	1550527	-----	
	1959-64	Elbow (right-angle), heater hose to water manifold, most models,	1692762	\$13 ea	
	1959-64	Water manifold hose fitting,	1548305	\$13 ea	
	1961-66	Heater core housing to body seal for cars with Climatizer,	1339224	\$12 ea	
	1963-64	Heater plenum (fibreglass) to inner guard seals, for Hawk, 1959-60 Lark & 1960-64 Champ pick up (2 pieces),	1332334	\$14 set	
	1962-66	Heater motor for sedans & 1960-64 Champ pick-up, will fit 1959-61 Larks,	1561418	\$155 ea	
	1963-85	Heater motor for Avanti,	1556924	\$255 ea	
	1950-66	Heater valve (tap) diaphragm kit to repair most U.S type Ranco heater valves,	SQ-0080	\$35 kit	
		Various complete used heaters are also in stock. Call for description.			
Air Conditioning Parts	1961-64	Compressor mounting bracket for all V8's with York compressor,	1553606	\$295 ea	
	1962-64	Plastic chrome vent bezels for all models, restores the appearance of your original air conditioning unit,	1558074	\$14 ea	
	1962-64	Evaporator side plastic vents, used,	1351242	\$14 ea	
	1962-64	Evaporator to dash support bracket, for all models (2 required),	1555697	\$15 ea	
	1963-64	Evaporator side support bracket for Hawks without climatizer,	1560126	\$20 pr	
	1957-64	V8 Air conditioning idler pulley mounting bolt, spacer & nut,	1552401	\$20 ea	
	1965-66	V8 Air conditioning idler pulley mounting bolt,	1565401	\$10 ea	
	1965-66	All models A/C idler pulley, will fit earlier models,	1565400	\$50 ea	
Climatizer Air Filters	1961-66	Sedan air filter, has rubber seal on edge,	1552094	\$40 ea	N.O.S.
	1963-64	Avanti air filter, has rubber seal on edge,	1556919	\$50 ea	N.O.S.
	1953-64	C & K mesh screen for front guard vent, nice reproduction,	285005P	\$20 ea	Reproduction

Radiator Hoses – Upper	1951-52	Champion,	530601	\$28 ea	 N.O.S. New mould New mould
	1953-55	Champion sedan & wagon,	532430	\$35 ea	
	1953-55	Commander & President sedan,	532174	\$35 ea	
	1953-55	Commander & President coupe,	532454	\$35 ea	
	1956-57	Hawk V8 (w/out supercharger),	1539157	\$15 ea	
	1958-60	Hawk V8 (w/out supercharger),	1544590	\$30 ea	
	1961-64	Hawk V8,	1550980	\$38 ea	
	1956-60	Sedan, Lark & Champ V8,	1544588	\$34 ea	
	1961-64	Lark & Cruiser V8,	1550652	\$38 ea	
	1965-66	Cruiser V8,	1563558	\$30 ea	
Radiator Hoses - Lower	1939-52	Champion, replaces 522160,	530881	\$35 ea	New mould
	1953-64	6 cyl sedans, replaces 533092 & 1539108,	1552785	\$35 ea	
	1953-55	Commander & President coupe,	532412	\$38 ea	
	1956-60	Hawk V8, exc. RHD with power steering,	1539129	\$38 ea	
	1961-64	Hawk V8 & 1956-60 RHD w/power steer.	1546378	\$40 ea	
	1956-60	Sedan, Lark & Champ V8,	1539109	\$35 ea	
	1961-66	Lark & Cruiser V8, replaces 1550654,	1564983	\$32 ea	
Hose Clamps	All models	Radiator hose clamps, zinc plated, Heater hose clamps,	G111616	\$2.50 ea	N.O.S.
	All models		G272852	\$2.50 ea	
Welsh Plugs	Most cars	1½ " Disc, fits 1939-58 Champion (1), 1934-50 Commander (6), and 1951-early 62 V8 (6),	1539038	\$4.50 ea	
	Most cars	1½" Cup, fits 1962-64 6 cyl (1) and 1962-64 V8 (6) including Avanti and Champ trucks,	1550386	\$5 ea	
Radiator Saddles	1956-64	Hawk saddle,	1312081P	\$150 ea	Used
	1961-66	Lark & Cruiser saddle, fits all except sliding roof wagon & convertible,	1338332P	\$250 ea	N.O.S.
	1960-64	Champ pick-up saddle,	1655218	\$125 ea	Used
Hawk Radiator Baffles	1956-64	Metal baffle bracket behind top tank of radiator,	1312475	\$40 ea	
	1956-64	Seal kit for above, includes staples, an important part that is often missing from Hawks,	1312475X1	\$25 kit	
Cooling System Cleaner & Neutralizer		Cleaner & Neutralizer, a Genuine Studebaker-Packard service product in original painted metal can, 16 oz.	SP-50009	\$20 ea	

