



Studebaker

AUTOMOTIVE SALES CORPORATION

SOUTH BEND 27, INDIANA

Service Letter

PARTS AND SERVICE

SUBJECT INSTRUMENT PANEL SWITCHES -
1965 MODEL PASSENGER CARS

FROM C. R. MC INTOSH, Manager
Technical Service Operations

NUMBER J-1965-4

DATE Feb. 11, 1965

Effective with car serial numbers C-111157 and C-511617, the instrument panel switches on 1965 model passenger cars have been changed. These new rocker type switches are an off-white color, similar to the 1964 models and early 1965 models; are made of a nylon material; but the exterior surface of the rocker is smooth.

Whenever a rocker switch replacement is required in a car with a serial number after those listed above, the following switches should be used:

<u>Part No.</u>	<u>Description</u>
1565148	Headlight Switch
1565149	(Instrument Light Switch (Heater and Defroster Switch
1565152	Windshield Wiper Switch

These parts are available, on order, from your Parts Depot.

rb